

INTERNAL ONLY

Issue: Temperature/Humidity sensor # added or removed


Product line: ACDA901

Environment:

Cause: An AP9520TH sensor has been detected. An AP9520TH sensor has been removed.

Resolution: This alarm occurs every time you add or remove a AP9520TH sensor on the a-link bus. Also you can get a removed alar if the sensor fails or the connection is disconnected.





Set the A-Link address

Set the DIP switches on each sensor to a unique A-Link address.

