

DRIVE FUSES CLASS J / CLASS T			
VOLTAGE	HP	FUSE AMPS	
200/250	1-2	15	
	3	20	
	5	35	
	7.5	60	
	10	70	
	15	70	
	20	90	
	25	110	
	30	125	
	40	175	
1F40	50	200	
	1-2	10	
	3	10	
1F41	5	20	
	7.5	25	
1F42	10	40	
	15	50	
	20	70	
	25	70	
	30	80	
	40	100	
	50	125	
	60	150	
	75	175	
	100	200	
Cutter - Hammer			P49621

Cutter-Hammer

P49620 Rev C

- L1 = Run
- L2 = NST
- L3 = not assigned
- R2 = Run
- tct = LEL

