

Edges of rear-plate end are higher than the surface of terminals.

NSX terminals shield.

Do not damage the highlighted circles area below



Partially cut squares can be removed to adapt to all types of connection for cables with lugs or copper bars, according to squares in dotted lines



In the leafleat, we can see that because of the bussbar or cable unsulation, partially cut could be made.

